Recovery Tank 4/19/2017, 1:37:14 PM

powered by measureQuick
www.measurequick.com



249.6 Microns	329.0 Microns	-0.0 Microns/s
Ultimate Pull Down	**Final Vacuum**	**Avg. Decay Rate**
1:22:52	0:47:58	2:10:51
Time to Ultimate P/D	**Time in Decay**	**Total Elapsed Time**

Customer

Jim Bergmann
Akron, Ohio 44319
Jimbergmann5@gmail.com

Equipment

Make: NRP

Model:
Recovery

Serial:
Tank

Other Stats

	Values
Avg. Ambient Temp:	79.1°F
Device Name:	BluVac+Pro_242
Date:	4/19/2017
Start Time:	1:37:14 PM
End Time:	3:48:06 PM